

COAST GARIBALDI			
Closure Date	Re-open Date	Facility Name & Address	Reason for Closure
November 18/15	PENDING	WEST COAST RESORTS – HOT TUB Louisa Cove, Bella Bella	Operating without a valid Permit A safety hazard exists (eg: suction hazard) A hazard exists that might compromise the general health of patrons (eg: air quality issue)
March 8	March 9	GREYSTONE LODGE SWIMMING POOL AND OUTDOOR WHIRLPOOL 4905 Spearhead PL, Whistler	Excessive disinfectant residual
May 30	PENDING	EAGLE'S NEST RESORT HOT TUB 3008 Esey RD, Anahim Lake	Insufficient/excessive disinfectant residual
July 31	August 1	ASPENS WHIRLPOOL (SLOPESIDE LARGE & SMALL) 4800 Spearhead DR, Whistler	Insufficient/excessive disinfectant residual

NORTH SHORE			
Closure Date	Re-open Date	Facility Name & Address	Reason for Closure
April 20/11	PENDING	WESTHILL VILLAS – WHIRLPOOL 2560 Westhill Close, West Vancouver	Minimum disinfectant residual is not being maintained
November 8/16	November 10/16	EDGEWATER WHIRLPOOL 2288 Bellevue AVE, West Vancouver	Insufficient/excessive disinfectant residual
August 15/17	November 24/17	OCEANBROOK APARTMENTS POOL & HOT TUB 1425 Esquimault , West Vancouver	Insufficient/excessive disinfectant residual
June 1	June 5	CENTREVIEW POOL AND HOT TUB 125 E 14 th ST	Insufficient/excessive disinfectant residual
June 27	June 27	CANYON COURT INN WHIRL POOL 1748 Capilano RD	Insufficient/excessive disinfectant residual
July 19	July 20	CENTREVIEW SWIMMING POOL 125 East 14 th ST	Main drain is not clearly visible at the bottom of the pool Insufficient/excessive disinfectant residual
July 27	August 28	EDGEWATER HOT TUB 2288 Bellevue, West Vancouver	Insufficient/excessive disinfectant residual



RICHMOND			
Closure Date	Re-open Date	Facility Name & Address	Reason for Closure
June 11/10	PENDING	WATER CUBE - SWIRL POOL 103-4411 No. 3 RD	Operating without a valid permit
July 14/15	PENDING	CLIPPER COVE – POOL 8700 Granville AVE	A safety hazard exists (eg: suction hazard)
August 16/17	Sept 1/17	PARK TOWERS "A" – OUTSIDE POOL 6651 Minoru BLVD	Insufficient disinfectant residual Inadequately trained operator
August 16/17	PENDING	PARK TOWERS "A" – SWIRL POOL 6651 Minoru BLVD	Insufficient disinfectant residual Inadequately trained operator
September 13/17	June 5	CARLETON PARK GARDENS Outside 10951 Mortfield RD	Main drain is not clearly visible at bottom of pool Recirculation system is not operational
March 1	March 2	SANDMAN INN – SWIRL 3233 St. Edwards DR	Excessive disinfectant residual
March 15	March 16	RIVA – WHIRLPOOL 5399 Cedarbridge WAY	Excessive disinfectant residual
April 5	April 6	RIVER CLUB – WADING POOL 11111 Horseshoe WAY	Excessive disinfectant residual
May 16	May 16	SHERATON AIRPORT VANCOUVER (SWIRL) 7551 Westminster HWY	Excessive disinfectant residual
June 5	June 5	RADISSON HOTEL VANCOUVER AIRPORT- SWIRL 8181 Cambie RD	Excessive disinfectant residual
August 10	August 17	CARLTON PARK GARDENS – OUTSIDE POOL 10951 Mortfield Road	Main drain is not clearly visible at bottom of pool



VANCOUVER			
Closure Date	Re-open Date	Facility Name & Address	Reason for Closure
March 3/16	PENDING	THE DELANO – WHIRLPOOL 3023 W 4 AVE	Minimum disinfectant residual is not being maintained
April 7/16	PENDING	GALILEO ON ROBSON – INDOOR WHIRLPOOL 822 Robson ST	A safety hazard exists (eg: suction hazard, electrical hazard)
March 22/17	PENDING	PACIFIC COVE APARTMENTS – INDOOR POOL 1202 Harwood ST	Insufficient/excessive disinfectant residual Inadequately trained operator
December 5/17	PENDING	GEC GRANVILLE -WHIRLPOOL 718 Drake ST	Insufficient/excessive disinfectant residual Inadequately trained operator
		LEWISH COMMUNITY CENTER	
January 18	January 19	JEWISH COMMUNITY CENTRE – WHIRLPOOL MEN'S 950 west 41 st AVE	Insufficient/excessive disinfectant residual
January 30	February 2	LANGARA ESTATES PHASE 2 –INDOOR POOL & WHIRLPOOL 6534 Pinehurst DR	Insufficient/excessive disinfectant residual
February 26	March 5	SURF CREST – INDOOR POOL 1251 Cardero ST	Minimum disinfectant residual is not being maintained
March 14	March 27	EL CID - INDOOR POOL 1850 Comox ST	Insufficient/excessive disinfectant residual
March 27	April 23	CHELSEA TERRACE INDOOR WHIRLPOOL 1040 Pacific ST	A safety hazard exists (eg: suction hazard, electrical hazard)
May 29	June 8	CONNAUGHT INDOOR POOL 1255 Pendrell ST	Insufficient/excessive disinfectant residual
May 29	June 4	HARLEY HOUSE INDOOR POOL 1230 Nelson ST	Lack of potable water/Water quality issue
June 18	June 19	PARKVIEW TOWERS 289 Drake ST	Insufficient/excessive disinfectant residual
July 23	July 24	FAIRMONT PACIFIC RIM SWIMMING POOL 1038 Canada PL	Insufficient/excessive disinfectant residual
August 7	August 8	SPECTRUM – CLUB OZONE WHIRPOOL 111 W. Georgia ST	Insufficient/excessive disinfectant residual



VANCOUVER			
Closure Date	Re-open Date	Facility Name & Address	Reason for Closure
August 7	August 8	FAIRMONT WATERFRONT HOTEL WHIRL POOL 900 Canada PL	Insufficient/excessive disinfectant residual
August 28	August 29	THE RITZ – WHIRL POOL 1211 Melville ST	Insufficient/excessive disinfectant residual
September 12	PENDING	CASSANDRA HOTEL – INDOOR WHIRLPOOL 3075 Kingsway	Insufficient/excessive disinfectant residual
September 14	September 17	MANHATTAN WEST – INDOOR POOL 1590 West 8 th AVE	Insufficient/excessive disinfectant residual
October 3	October 5	HOLIDAY INN – INDOOR POOL 1110 Howe ST	Insufficient/excessive disinfectant residual
October 15	October 24	CAMBRIDGE PLACE – OUTDOOR WHIRLPOOL 555 W. 14 th AVE	Insufficient/excessive disinfectant residual
October 17	PENDING	TWO HARBOUR GREEN – WHIRLPOOL 1139 W. Cordova ST	A safety hazard exists (eg: suction hazard, electrical hazard)
October 17	October 18	GOLD MEDAL CLUB – WHIRPOOL 148 Athletes WAY	Insufficient/excessive disinfectant residual
December 3	December 5	BEACH TOWERS 1600 Beach AVE	Insufficient/excessive disinfectant residual
December 4	December 5	THREE HARBOUR GREEN 277 Thurlow ST	Insufficient/excessive disinfectant residual
December 18	December 20	CLUB OASIS WHIRLPOOL 633 Kinghorne MEWS	Minimum disinfectant residual is not being maintained
December 18	PENDING	THE CRYSTALLIS – OUTDOOR POOL 1020 Harwood ST	Recirculation system is not operational
December 20	PENDING	HARBOURSIDE PARK – INDOOR POOL 588 Broughton ST	Insufficient/excessive disinfectant residual

To contact us with a compliment, complaint or query: environmental.health@vch.ca